

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Const. of Sai temple community hall  
**Work Code :** OD/369/3538/120913/409612/00073615  
**Work Category :** Building/ Community Centre  
**District Name :** Puri  
**Block Name :** Delanga  
**Gram Panchayat Name :** Dhankera  
**Village Name :** Dhanakera(Egarapana)

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299925.63002718/- (Two lakh ninety nine thousand nine hundred twenty five rupees six three zero zero two seven one eight zero two paise only), vide TSR No OD/369/3538/120913/409612/00073615/TS dated: 09-02-2026.

**Technical sanction given by :** DHARMENDRA KUMAR SAMANTARAY, JE, Delanga.