

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of Bhoga Mandap at Sankat Tarini Temple

Work Code : OD/363/3471/119803/428971/00068979

Work Category : Religious Structures/ Religious Structures

District Name : Koraput

Block Name : Koraput

Gram Panchayat Name : Kerenga

Village Name : Kerenga

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 449999.70704336/-(Four lakh forty nine thousand nine hundred ninety nine rupees seven zero seven zero four three three six paise only), vide TSR No OD/363/3471/119803/428971/00068979/TS dated: 11-02-2026.

Technical sanction given by : P Santosh Kumar Patro, JE, Koraput.