

TECHNICAL SANCTION FOR WORKS

Work Name : Improvement of CC road from incomplete CC road to Baya Prusty house

Work Code : OD/346/3304/275580/393451/00071511

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Khaira

Gram Panchayat Name : Dalanga-li

Village Name : Dalanga-l

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 111999.97972703/-(One lakh eleven thousand nine hundred ninety nine rupees nine seven nine seven two seven zero three paise only), vide TSR No OD/346/3304/275580/393451/00071511/TS dated: 14-02-2026.

Technical sanction given by : Santosh Kumar Prusty, JE, Khaira.