

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Improvement of CC road with guard wall from pubansa chandana pokhari to bhagabat tungi

**Work Code :** OD/350/3342/117076/399783/00101555

**Work Category :** Building/ Bhagabat Tungi

**District Name :** Cuttack

**Block Name :** Nischinta Koili

**Gram Panchayat Name :** Asueresswar

**Village Name :** Kulagan-Isalo

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 387667.60249867/- (Three lakh eighty seven thousand six hundred sixty seven rupees six zero two four nine eight six seven paise only), vide TSR No OD/350/3342/117076/399783/00101555/TS dated: 11-03-2026.

**Technical sanction given by :** Pradeep Kumar Senapati, JE, Nischinta Koili.