

TECHNICAL SANCTION FOR WORKS

Work Name : Installation of Solar LED Mini Mast Light near Hendulai Temple of Kula Bhansara, GP-Kanimula

Work Code : OD/355/3393/118221/397476/00104195

Work Category : Rural Electrification/ LED Street Lighting

District Name : Jagatsinghpur

Block Name : Tirtol

Gram Panchayat Name : Kanimula

Village Name : Bhansar

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 99999.995875021/- (Ninety nine thousand nine hundred ninety nine rupees nine nine five eight seven five zero two zero six six paise only), vide TSR No OD/355/3393/118221/397476/00104195/TS dated: 22-03-2026.

Technical sanction given by : PRASANT KUMAR PADHI, JE, Tirtol.