

ADMINISTRATIVE/FINANCIAL SANCTION FOR WORKS

Work Name : Repair/Restoration of Hanuman Temple at Maliguda, Manbar

Work Code : OD/363/3471/119807/428998/00062788

Work Category : Religious Structures/ Religious Structures

District Name : Koraput

Block Name : Koraput

Gram Panchayat Name : Manbar

Village Name : Manbar

Considering Importance and necessity of the work and resolute by the District, Koraput and Technically Approved / Sanctioned vide TSR No OD/363/3471/119807/428998/00062788/TS, Dt: 19-01-2026 the estimate of the proposed work has been accorded Administrative Sanction for Rs 299999.17088634/- (Two lakh ninety nine thousand nine hundred ninety nine rupees one seven zero eight eight six three three six paise only) vide Proceedings No. OD/363/3471/119807/428998/00062788/AS Dt: 19-01-2026.

Administrative sanction given by : Dr. DEBASIS GOUDA(BDO), Koraput.