

TECHNICAL SANCTION FOR WORKS

Work Name : Repair of Culvert & road at Dedespali New road

Work Code : OD/366/3517/120495/427970/00014219

Work Category : CD Work/ Slab Culvert

District Name : Nabarangpur

Block Name : Nabarangpur

Gram Panchayat Name : Pujariguda

Village Name : Dedesapali

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 99999.9/-(ninety nine thousand nine hundred ninety nine rupees and ninety paise), vide TSR No OD/366/3517/120495/427970/00014219/TS dated: 16-11-2024.

Technical sanction given by : BINOD BEHERA, JE, Nabarangpur.