

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Maintenance of AWC Building At Mahulapalli

Work Code : OD/354/3368/117654/410447/00064038

Work Category : Building/ AWC

District Name : Ganjam

Block Name : Buguda

Gram Panchayat Name : Arakhapur

Village Name : Mahulapali

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 44998.841405568/- (Forty four thousand nine hundred ninety eight rupees eight four one four zero five five six seven eight four four paise only), vide TSR No OD/354/3368/117654/410447/00064038/TS dated: 13-11-2025.

Technical sanction given by : Prasan Kumar Sahu, JE, Buguda.