

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of culvert at Ninhan Munda sahi

Work Code : OD/361/3453/119492/385689/00063996

Work Category : CD Work/ Slab Culvert

District Name : Kendujhar

Block Name : Patana

Gram Panchayat Name : Turumunga

Village Name : Ninhua

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 499999.69743265/- (Four lakh ninety nine thousand nine hundred ninety nine rupees six nine seven four three two six five paise only), vide TSR No OD/361/3453/119492/385689/00063996/TS dated: 14-11-2025.

Technical sanction given by : Phillip Kumar Mohanta, JE, Patana.