

## TECHNICAL SANCTION FOR WORKS

**Work Name :** REPAIR AND MAINTAINANCE OF ROAD FROM BHAGIRATHA MOHANTY CHHAK TO BANAMALI PRADHAN CHHAK AT VIILAGE-NARAYANPUR.

**Work Code :** OD/346/3300/116100/392145/00064890

**Work Category :** Road/ CC Road

**District Name :** Balasore

**Block Name :** Baliapal

**Gram Panchayat Name :** Betagadia

**Village Name :** Narayanpur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 96408.413693454/- (Ninety six thousand four hundred eight rupees four one three six nine three four five three five nine paise only), vide TSR No OD/346/3300/116100/392145/00064890/TS dated: 17-11-2025.

**Technical sanction given by :** DAMBARUDHAR NAYAK, JE, Baliapal.