

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and restoration of road from Purna Chandra Pradhan house to Malati Bhol house

Work Code : OD/346/3309/116314/393717/00063572

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Soro

Gram Panchayat Name : Gopinathpur

Village Name : Raghunathpur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 20999.993039728/-(Twenty thousand nine hundred ninety nine rupees nine nine three zero three nine seven two eight paise only), vide TSR No OD/346/3309/116314/393717/00063572/TS dated: 17-11-2025.

Technical sanction given by : Rojalin Jena , JE, Soro.