

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and Restoration of Culvert at Padmapokhari

Work Code : OD/346/3309/116318/393765/00065702

Work Category : CD Work/ Slab Culvert

District Name : Balasore

Block Name : Soro

Gram Panchayat Name : Madhusuidanpur

Village Name : Kurunia

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 59999.993796163/- (Fifty nine thousand nine hundred ninety nine rupees nine nine three seven nine six one six three zero zero six paise only), vide TSR No OD/346/3309/116318/393765/00065702/TS dated: 23-11-2025.

Technical sanction given by : Monalisa Pati , JE, Soro.