

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair of Basudeipur Pry School  
**Work Code :** OD/346/3309/116329/393778/00066164  
**Work Category :** Building/ Elementary School  
**District Name :** Balasore  
**Block Name :** Soro  
**Gram Panchayat Name :** Sarasakha  
**Village Name :** Basudeipur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 199999.99127381/- (One lakh ninety nine thousand nine hundred ninety nine rupees nine nine one two seven three eight one paise only), vide TSR No OD/346/3309/116329/393778/00066164/TS dated: 27-11-2025.

**Technical sanction given by :** Taruna Kumar Nandi , JE, Soro.