

## TECHNICAL SANCTION FOR WORKS

**Work Name :** repair and restoration of road from Asta Gachha to Ranjit sahi Nadi ghata

**Work Code :** OD/346/3305/116250/393098/00065364

**Work Category :** Road/ CC Road

**District Name :** Balasore

**Block Name :** Nilgiri

**Gram Panchayat Name :** Radhakishorepur

**Village Name :** Pundala

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 59999.138355784/- (Fifty nine thousand nine hundred ninety nine rupees one three eight three five five seven eight four paise only), vide TSR No OD/346/3305/116250/393098/00065364/TS dated: 14-12-2025.

**Technical sanction given by :** Bharat Singh, JE, Nilgiri.