

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair and restoration of Bhagahmara Primary school

**Work Code :** OD/346/3305/116240/393154/00065366

**Work Category :** Building/ Elementary School

**District Name :** Balasore

**Block Name :** Nilgiri

**Gram Panchayat Name :** Jamudiha

**Village Name :** Jamudihi

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 149999.11244972/-(One lakh forty nine thousand nine hundred ninety nine rupees one one two four four nine seven two paise only), vide TSR No OD/346/3305/116240/393154/00065366/TS dated: 14-12-2025.

**Technical sanction given by :** BAIDYANATH SINGH, JE, Nilgiri.