

TECHNICAL SANCTION FOR WORKS

Work Name : Repairing of AWC building at Dalsora
Work Code : OD/365/3488/120072/387531/00067633
Work Category : Building/ AWC
District Name : Mayurbhanj
Block Name : Bahalda
Gram Panchayat Name : Bhitaramda
Village Name : Dalasora

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 202037.45710033/- (Two lakh two thousand thirty seven rupees four five seven one zero zero three three paise only), vide TSR No OD/365/3488/120072/387531/00067633/TS dated: 22-12-2025.

Technical sanction given by : PRAFULLA KUMAR BED, JE, Bahalda.