

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Const of Boundar Wall Near Dandapatini Temple Dahagaon

**Work Code :** OD/358/3417/118771/424000/00065387

**Work Category :** Other Infrastructure/ Boundary Wall

**District Name :** Kalahandi

**Block Name :** Kokasara

**Gram Panchayat Name :** Dahagaon

**Village Name :** Dahagan

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 352396.95214038/-(Three lakh fifty two thousand three hundred ninety six rupees nine five two one four zero three eight paise only), vide TSR No OD/358/3417/118771/424000/00065387/TS dated: 28-12-2025.

**Technical sanction given by :** Kirti Ranjan Behera, JE, Kokasara.