

TECHNICAL SANCTION FOR WORKS

Work Name : repair and maint. of barahi PM School at bancho

Work Code : OD/361/3449/119387/387061/00066679

Work Category : Building/ Elementary School

District Name : Kendujhar

Block Name : Hatadihi

Gram Panchayat Name : Bancho

Village Name : Bancho

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 229999.99542498/-(Two lakh twenty nine thousand nine hundred ninety nine rupees nine nine five four two four nine seven five paise only), vide TSR No OD/361/3449/119387/387061/00066679/TS dated: 04-01-2026.

Technical sanction given by : PRAFULLA CHANDRA BEHERA, JE, Hatadihi.