

TECHNICAL SANCTION FOR WORKS

Work Name : Const of Protection Wall with CC Road from Sudev Das House to Taruna Mallik House VillGPKuligan

Work Code : OD/346/3307/116277/392863/00072721

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Remuna

Gram Panchayat Name : Kuligan

Village Name : Kuligan

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 449999.99414415/-(Four lakh forty nine thousand nine hundred ninety nine rupees nine nine four one four four one five paise only), vide TSR No OD/346/3307/116277/392863/00072721/TS dated: 05-01-2026.

Technical sanction given by : MAHENDRA KUMAR SAMAL, JE, Remuna.