

## TECHNICAL SANCTION FOR WORKS

**Work Name :** R/R near Car Computer Baharbil Culvert

**Work Code :** OD/348/3327/116728/395288/00071339

**Work Category :** CD Work/ Slab Culvert

**District Name :** Bhadrak

**Block Name :** Dhamanagar

**Gram Panchayat Name :** Dhusuri

**Village Name :** Dhusuri

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 59999.087396118/- (Fifty nine thousand nine hundred ninety nine rupees zero eight seven three nine six one one seven eight eight paise only), vide TSR No OD/348/3327/116728/395288/00071339/TS dated: 10-01-2026.

**Technical sanction given by :** PRAVAT KUMAR BEHERA, JE, Dhamanagar.