

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and restoration of road from Sahara sahi chhaka to Bhagirathi ojha house

Work Code : OD/346/3305/116240/393154/00073767

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Nilgiri

Gram Panchayat Name : Jamudiha

Village Name : Jamudihi

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 119999.67520633/-(One lakh nineteen thousand nine hundred ninety nine rupees six seven five two zero six three three paise only), vide TSR No OD/346/3305/116240/393154/00073767/TS dated: 17-01-2026.

Technical sanction given by : BAIDYANATH SINGH, JE, Nilgiri.