

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Const. of Community hall at Senapati Sahi Jogamaya Temple

**Work Code :** OD/369/3538/275134/408578/00071352

**Work Category :** Building/ Community Centre

**District Name :** Puri

**Block Name :** Delanga

**Gram Panchayat Name :** Khelaur

**Village Name :** Brahmanataraboi

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 626743.87693152/-(Six lakh twenty six thousand seven hundred forty three rupees eight seven six nine three one five two paise only), vide TSR No OD/369/3538/275134/408578/00071352/TS dated: 20-01-2026.

**Technical sanction given by :** SUBRAT KUMAR BARIK (AEE), Delanga.