

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of Culvert at Tentuli gachha chowk at Nuagada in Convergence with MGNREGA

Work Code : OD/353/3361/117528/414210/00070875

Work Category : CD Work/ Slab Culvert

District Name : Gajapati

Block Name : Nuagada

Gram Panchayat Name : Nuagada

Village Name : Nuagada

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.99805835/- (Two lakh ninety nine thousand nine hundred ninety nine rupees nine nine eight zero five eight three five paise only), vide TSR No OD/353/3361/117528/414210/00070875/TS dated: 23-01-2026.

Technical sanction given by : Sarbeswar Sahu, JE, Nuagada.