

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair and maintenance of Block Colony Staff Quarter , Gudari

**Work Code :** OD/370/3549/121133/426933/00067194

**Work Category :** Building/ Staff Quarter

**District Name :** Rayagada

**Block Name :** Gudari

**Gram Panchayat Name :** Asada

**Village Name :** Bamuni Dangar

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 268341.81417817/- (Two lakh sixty eight thousand three hundred forty one rupees eight one four one seven eight one seven paise only), vide TSR No OD/370/3549/121133/426933/00067194/TS dated: 28-01-2026.

**Technical sanction given by :** P Mohan Rao Patro, JE, Gudari.