

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Maintenance of Muruga-2 AWC Building

Work Code : OD/352/3349/117246/402556/00069237

Work Category : Building/ AWC

District Name : Dhenkanal

Block Name : Bhuban

Gram Panchayat Name : Gada Nrusingha Prasad

Village Name : Muruga

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 44998.575015498/- (Forty four thousand nine hundred ninety eight rupees five seven five zero one five four nine eight paise only), vide TSR No OD/352/3349/117246/402556/00069237/TS dated: 30-01-2026.

Technical sanction given by : Girish Kumar Parida, JE, Bhuban.