

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of Rest Room and Stage at Khuntmunda Volley Ball Field

Work Code : OD/373/3589/121782/383718/00072524

Work Category : Other Infrastructure/ Play Field

District Name : Sundargarh

Block Name : Tangarpali

Gram Panchayat Name : Ujalpur

Village Name : Khuntamunda

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 624939.56732655/- (Six lakh twenty four thousand nine hundred thirty nine rupees five six seven three two six five five paise only), vide TSR No OD/373/3589/121782/383718/00072524/TS dated: 03-02-2026.

Technical sanction given by : MANAS NETI(AEE), Tangarpali.