

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of Guard wall from Bhuktu house to Gopal house at Bhalukiasahi

Work Code : OD/365/3489/120086/389566/00071402

Work Category : Water Body/ Guard Wall or Retaining Wall or Protection Wall

District Name : Mayurbhanj

Block Name : Bangriposi

Gram Panchayat Name : Dhobanisole

Village Name : Dhobanisul

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 728582.99296835/- (Seven lakh twenty eight thousand five hundred eighty two rupees nine nine two nine six eight three five paise only), vide TSR No OD/365/3489/120086/389566/00071402/TS dated: 04-02-2026.

Technical sanction given by : Suvendu Kumar Naik(AEE), Bangriposi.