

## TECHNICAL SANCTION FOR WORKS

**Work Name :** CONST OF BHOGA MANDAPA RAM MANDIR AT TERANTI

**Work Code :** OD/361/3452/119471/386009/00068083

**Work Category :** Religious Structures/ Religious Structures

**District Name :** Kendujhar

**Block Name :** Kendujhar Sadar

**Gram Panchayat Name :** Sankiri

**Village Name :** Teranti

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.99410482/- (Two lakh ninety nine thousand nine hundred ninety nine rupees nine nine four one zero four eight two paise only), vide TSR No OD/361/3452/119471/386009/00068083/TS dated: 10-03-2026.

**Technical sanction given by :** Ratikanta Lenka, JE, Kendujhar Sadar.