

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair & Maintenance of Baushanta AWC Building

**Work Code :** OD/356/3402/118471/401482/00109637

**Work Category :** Building/ AWC

**District Name :** Jajpur

**Block Name :** Rasulpur

**Gram Panchayat Name :** Jabara

**Village Name :** Bausantabada

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 44999.662543441/- (Forty four thousand nine hundred ninety nine rupees six six two five four three four four zero nine nine four paise only), vide TSR No OD/356/3402/118471/401482/00109637/TS dated: 15-03-2026.

**Technical sanction given by :** SASMITA NAYAK, JE, Rasulpur.