

TECHNICAL SANCTION FOR WORKS

Work Name : SATEIBHANJHA COMMUNITY SHED AT HUNDULA

Work Code : OD/361/3452/119466/385992/00068076

Work Category : Other Infrastructure/ Parking shed

District Name : Kendujhar

Block Name : Kendujhar Sadar

Gram Panchayat Name : Palaspanga

Village Name : Hundula

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 499999.99586622/- (Four lakh ninety nine thousand nine hundred ninety nine rupees nine nine five eight six six two two paise only), vide TSR No OD/361/3452/119466/385992/00068076/TS dated: 17-03-2026.

Technical sanction given by : Ranjan Kumar Swain, JE, Kendujhar Sadar.