

TECHNICAL SANCTION FOR WORKS

Work Name : Constn. of Drain from Abhiram Behera house to Dinabandhu Moharana house at Dalanga-II

Work Code : OD/346/3304/275580/393452/00105622

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Khaira

Gram Panchayat Name : Dalanga-li

Village Name : Dalanga-li

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 151918.91088446/-(One lakh fifty one thousand nine hundred eighteen rupees nine one zero eight eight four four six paise only), vide TSR No OD/346/3304/275580/393452/00105622/TS dated: 18-03-2026.

Technical sanction given by : Santosh Kumar Prusty, JE, Khaira.