

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair of Bhapur Market Complex  
**Work Code :** OD/367/3523/120593/406127/00111491  
**Work Category :** Building/ Market Complex  
**District Name :** Nayagarh  
**Block Name :** Bhapur  
**Gram Panchayat Name :** Bhapur  
**Village Name :** Bhapur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 199999.64586937/-(One lakh ninety nine thousand nine hundred ninety nine rupees six four five eight six nine three seven paise only), vide TSR No OD/367/3523/120593/406127/00111491/TS dated: 23-03-2026.

**Technical sanction given by :** Santosh Kumar Mallick, JE, Bhapur.