

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and restoration of road from turania chhaka rd road to brundaban majhi house

Work Code : OD/346/3305/116248/393279/00105722

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Nilgiri

Gram Panchayat Name : Narenpur

Village Name : Naranpur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 23999.901961312/- (Twenty three thousand nine hundred ninety nine rupees nine zero one nine six one three one two paise only), vide TSR No OD/346/3305/116248/393279/00105722/TS dated: 31-03-2026.

Technical sanction given by : AJAY SOREN, JE, Nilgiri.