ADMINISTRATIVE/FINANCIAL SANCTION FOR WORKS

Work Name : CC Drain at Paraja sahi to Gadaba sahi of Bhitardusura
Work Code : OD/363/3479/119917/429848/00069367
Work Category : CD Work/ Drain Masonry or Cement Concrete
District Name : Koraput
Block Name : Semiliguda
Gram Panchayat Name : Hataguda
Village Name : Dusura

Considering Importance and necessity of the work and resolute by the District, Koraput and Technically Approved / Sanctioned vide TSR No OD/363/3479/119917/429848/00069367/TS, Dt: 09-01-2026 the estimate of the proposed work has been accorded Administrative Sanction for Rs 367199.60914692/- (Three lakh sixty seven thousand one hundred ninety nine rupees six zero nine one four six nine one six eight three paise only) vide Proceedings No. OD/363/3479/119917/429848/00069367/AS Dt: 09-01-2026.

Administrative sanction given by : JASHMIN KUMAR PRADHAN(BDO), Semiliguda.