

TECHNICAL SANCTION FOR WORKS

Work Name : Imp of Play Ground at Bidighat

Work Code : OD/345/3285/115782/420275/00014442

Work Category : Other Infrastructure/ Play Field

District Name : Balangir

Block Name : Balangir

Gram Panchayat Name : Bidighat

Village Name : Bidighat

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.4174257/-(two lakh ninety nine thousand nine hundred ninety nine rupees and forty two paise), vide TSR No OD/345/3285/115782/420275/00014442/TS dated: 28-02-2025.

Technical sanction given by : Rasmita Mohanty, JE, Balangir.