

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & maintenance of govt. UP school Daupali

Work Code : OD/345/3285/115785/420189/00015311

Work Category : Building/ Elementary School

District Name : Balangir

Block Name : Balangir

Gram Panchayat Name : Chudapali

Village Name : Daupali

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 199999.56296015/-(one lakh ninety nine thousand nine hundred ninety nine rupees and fifty six paise), vide TSR No OD/345/3285/115785/420189/00015311/TS dated: 03-03-2025.

Technical sanction given by : Bipin kumar Rout, JE, Balangir.