

TECHNICAL SANCTION FOR WORKS

Work Name : Repairing Of Mandap At Uparpada,Khuntpali

Work Code : OD/347/3312/116386/380638/00016496

Work Category : Building/ Kalyan Mandap

District Name : Bargarh

Block Name : Bargarh

Gram Panchayat Name : Khuntpali

Village Name : Khuntpali

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 199999.7672109/-(One lakh ninety nine thousand nine hundred ninety nine point seven six seven two one zero nine paise only), vide TSR No OD/347/3312/116386/380638/00016496/TS dated: 29-03-2025.

Technical sanction given by : SANTOSH KUMAR BEHERA, JE, Bargarh.