

TECHNICAL SANCTION FOR WORKS

Work Name : Improvement Of Brahmani Tank At Kendubahara

Work Code : OD/368/3534/120841/421676/00016560

Work Category : Water Body/ Embankment

District Name : Nuapada

Block Name : Nuapada

Gram Panchayat Name : Kendubahara

Village Name : Chhotkendubahara

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 399930.2/- (Three lakh ninety nine thousand nine hundred thirty rupees two paise only), vide TSR No OD/368/3534/120841/421676/00016560/TS dated: 04-06-2025.

Technical sanction given by : ARUN SAHU(AEE), Nuapada.