

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and Maintenance of Dadaki UP School Building

Work Code : OD/359/3430/118979/415443/00013531

Work Category : Building/ Elementary School

District Name : Kandhamal

Block Name : Phulbani

Gram Panchayat Name : Dadaki

Village Name : Dadaki

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.5755642/- (Two lakh ninety nine thousand nine hundred ninety nine rupees five seven five five six four two paise only), vide TSR No OD/359/3430/118979/415443/00013531/TS dated: 12-06-2025.

Technical sanction given by : SANTOSHI SAHOO, JE, Phulbani.