

TECHNICAL SANCTION FOR WORKS

Work Name : Const. of CC road with Guard wall from Badebali to Tadri

Work Code : OD/359/3430/118983/415424/00013535

Work Category : Water Body/ Guard Wall or Retaining Wall or Protection Wall

District Name : Kandhamal

Block Name : Phulbani

Gram Panchayat Name : Jamjhari

Village Name : Jamujhari

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.63110341/-(Two lakh ninety nine thousand nine hundred ninety nine rupees six three one one zero three four one paise only), vide TSR No OD/359/3430/118983/415424/00013535/TS dated: 26-07-2025.

Technical sanction given by : ANANDA KUMAR MEHER, JE, Phulbani.