

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Maintenance of AWC at Gumura

Work Code : OD/361/3452/119461/386165/00015623

Work Category : Building/ AWC

District Name : Kendujhar

Block Name : Kendujhar Sadar

Gram Panchayat Name : Mandua

Village Name : Gumura

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 44999.287056224/- (Forty four thousand nine hundred ninety nine rupees two eight seven zero five six two two four paise only), vide TSR No OD/361/3452/119461/386165/00015623/TS dated: 06-10-2025.

Technical sanction given by : Kandarpa Palei, JE, Kendujhar Sadar.