

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair & Maintenance of AWC at Ghuturu-2

**Work Code :** OD/361/3452/119461/386168/00015625

**Work Category :** Building/ AWC

**District Name :** Kendujhar

**Block Name :** Kendujhar Sadar

**Gram Panchayat Name :** Mandua

**Village Name :** Ghuturu

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 44999.716649733/- (Forty four thousand nine hundred ninety nine rupees seven one six six four nine seven three three paise only), vide TSR No OD/361/3452/119461/386168/00015625/TS dated: 10-10-2025.

**Technical sanction given by :** Kandarpa Palei, JE, Kendujhar Sadar.