

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of Gourd wall at MV-7 pond
Work Code : OD/364/3484/120005/430269/00063756
Work Category : Water Body/ Guard Wall or Retaining Wall or Protection Wall
District Name : Malkangiri
Block Name : Malkangiri
Gram Panchayat Name : Tamasa
Village Name : Jaganathpali (M.V.-7)

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 399999.21942134/-(Three lakh ninety nine thousand nine hundred ninety nine rupees two one nine four two one three four three five paise only), vide TSR No OD/364/3484/120005/430269/00063756/TS dated: 06-11-2025.

Technical sanction given by : TAPAN KUMAR SAMAL, JE, Malkangiri.