

TECHNICAL SANCTION FOR WORKS

Work Name : REPAIR AND MAINTENANCE OF AWC AT BISUBHATTA

Work Code : OD/363/3473/275096/429159/00064406

Work Category : Building/ AWC

District Name : Koraput

Block Name : Kundura

Gram Panchayat Name : P Hulabhata

Village Name : Phulabhata

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 44933.253168244/-(Forty four thousand nine hundred thirty three rupees two five three one six eight two four three nine eight paise only), vide TSR No OD/363/3473/275096/429159/00064406/TS dated: 12-11-2025.

Technical sanction given by : NAYANA PATNAIK, JE, Kundura.