

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Construction of Protection wall at Langalpai

**Work Code :** OD/370/3553/121193/426262/00064615

**Work Category :** Road/ CC Road

**District Name :** Rayagada

**Block Name :** Kolnara

**Gram Panchayat Name :** Badakhilapadar

**Village Name :** Nangalpalli

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 220726.85623219/- (Two lakh twenty thousand seven hundred twenty six rupees eight five six two three two one nine four four paise only), vide TSR No OD/370/3553/121193/426262/00064615/TS dated: 17-11-2025.

**Technical sanction given by :** Babulu Hembram, JE, Kolnara.