

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and maintenance of UPS Gunduribadi

Work Code : OD/354/3385/275061/410907/00065262

Work Category : Building/ Elementary School

District Name : Ganjam

Block Name : Surada

Gram Panchayat Name : Bhagabanpur

Village Name : Gunduribadi

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 149999.2265072/- (One lakh forty nine thousand nine hundred ninety nine rupees two two six five zero seven two zero two three paise only), vide TSR No OD/354/3385/275061/410907/00065262/TS dated: 19-11-2025.

Technical sanction given by : Kanheaya kar, JE, Surada.