

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of Addl. Class Room At UP School, Karachuli

Work Code : OD/354/3368/117665/410364/00063811

Work Category : Building/ Elementary School

District Name : Ganjam

Block Name : Buguda

Gram Panchayat Name : Karachuli

Village Name : Karachuli

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 999999.76993218/- (Nine lakh ninety nine thousand nine hundred ninety nine rupees seven six nine nine three two one eight paise only), vide TSR No OD/354/3368/117665/410364/00063811/TS dated: 20-11-2025.

Technical sanction given by : Rajib Chandra Pradhan(AEE), Buguda.