

TECHNICAL SANCTION FOR WORKS

Work Name : repair and renovation of road from babandha banion tree to deuchakhali tank

Work Code : OD/346/3305/116252/393162/00065535

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Nilgiri

Gram Panchayat Name : Siadimal

Village Name : Siadimal

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 59999.079570046/- (Fifty nine thousand nine hundred ninety nine rupees zero seven nine five seven zero zero four six paise only), vide TSR No OD/346/3305/116252/393162/00065535/TS dated: 26-11-2025.

Technical sanction given by : SANJEEB KUMAR PANDA, JE, Nilgiri.