

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and Restoration of road from RD road to Mission shakti building

Work Code : OD/346/3298/116058/394018/00062816

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Bahanaga

Gram Panchayat Name : Kuruda

Village Name : Kuruda

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 59992.015990024/-(Fifty nine thousand nine hundred ninety two rupees zero one five nine nine zero zero two four paise only), vide TSR No OD/346/3298/116058/394018/00062816/TS dated: 29-11-2025.

Technical sanction given by : PRASANTA GHADAI, JE, Bahanaga.