

TECHNICAL SANCTION FOR WORKS

Work Name : repair and restoration of road from swpneswar temple to badapalsa berhampur

Work Code : OD/346/3305/116233/393261/00068468

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Nilgiri

Gram Panchayat Name : Berhampur

Village Name : Berhampur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 119999.72408363/-(One lakh nineteen thousand nine hundred ninety nine rupees seven two four zero eight three six three paise only), vide TSR No OD/346/3305/116233/393261/00068468/TS dated: 14-12-2025.

Technical sanction given by : Ramesh Singh, JE, Nilgiri.